

Technical drawing of a motor showing three views: a side view, a front view, and a top view. The side view shows dimensions TBS, TBW, N, R, E, T, L, and AC. The top view shows dimensions TBH, kk, M, P, 4-S, and HD. A detail view of the mounting flange shows dimensions F, D, and G.

[illegible][illegible]